



How To Measure A Radius Corner

Step A. Draw a straight line from the both edges as follows:



Step B. Draw another line from where the curve begins as follows:



Step C. Measure the distance between Line A and Line B to give you the Radius dimension.

